Fastex Gun Care

Fastex Moly Remover

Fastex FCMR

Key Features

- Quick and easy to apply
- Fast acting
- Water soluble

Fastex Moly Remover is specially formulated for the removal of Molybdenum Disulfide (Moly) from firearms. It is supplied in an undiluted form and ***requires mixing with clean water before use.***

Do not use Fastex Moly Remover at full strength. Fastex Moly Remover is designed to be diluted with clean water as follows:

MIXING:

Put 2 parts clean water (by volume) into a clean container. While stirring, pour 1 part **Fastex Moly Remover** (by volume) INTO the water. To ensure correct dispersion continue stirring the mixture for at least 1 minute at which time it will turn white in color.

Note: Correct mixing requires this 1-minute stirring.

APPLICATION:

Take the mixed **Fastex Moly Remover** and using a wet patch, apply it to your rifle barrel. After thoroughly wetting the rifle bore; allow it to sit for 2 to 3 minutes.

Using a bronze bore brush, scrub out the bore while applying additional amounts of **Fastex Moly Remover** to the bronze bore brush. After a good brushing, patch out debris and residue as it loosens, repeating the cleaning process as the layers of Moly and other deposits start to loosen. Always patch out any residue before continuing further applications of Fastex Moly Remover.

Wipe off any surplus **Fastex Moly Remover** from any wood or composite components of the firearm at the end of the cleaning process.

During this cleaning process **Fastex Moly Remover** will also remove any chemical or oil coatings that may have been previously used to treat the firearm. After using **Fastex Moly Remover** it is essential that all metal surfaces be lubricated before storing or reuse.

Note: Fastex Moly Remover should **always** be used as a mixture.

Tip: In most cases, the handling of Molybdenum Disulfide (Moly) can be a dirty job and may be difficult to remove from your skin. Apply **Fastex B4 hand®** Skin Barrier cream to your hands before you start any cleaning process and dirt, grime and residue can be simply washed away with soap and water **without the need for hand cleaners.**

©2006-2012 Fastex & B4 hand (logo, text, legend & design) being registered trademarks, owned by Glenveigh Limited

www.fastexlubes.com